

Equipment Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.7

Report Date: January 2, 2013

Calendar Quarter: 4th Quarter 2012

Safety Recall Quarterly Report from October 1, 2012 through December 31, 2012

Manufacturer: The Goodyear Tire & Rubber Company

Report Author: Simeon S Ford, Manager Global Regulations, Standards & Compliance

Phone: (330) 796-3519

Recall Subject: Six Sizes Wrangler Silent Armor Tires

49 CFR Part 573.7

- (1) The notification campaign number assigned by NHTSA 12T003000
- (2) The date notification began and the date completed. Began: March 1, 2012 Completed: Mar 23, 2012
- (3) The number of vehicles or items of equipment involved in the notification campaign. 40,915
- (4) The number of vehicles and equipment items which have been inspected and repaired 2,957
and the number of vehicles and equipment items inspected and determined not to need repair. 3,747
- (5) The number of vehicles or items of equipment determined to be unreachable for inspection due to export, theft, scrapping, failure to receive notification, or other reasons (specify). The number of vehicles or items or equipment in each category shall be specified. 0
- (6) The number of items of equipment repaired and/or returned by dealers, other retailers, and distributors to the manufacturer prior to their first sale to the public. 59
- (7) For all recalls that involve the replacement of tires, the manufacturer shall provide:
 - (i) The aggregate number of recalled tires that the manufacturer becomes aware have not been rendered unsuitable for resale for installation on a motor vehicle in accordance with the manufacturer's plan provided to NHTSA pursuant to §573.6(c)(9), 0
 - (ii) The aggregate number of recalled tires that the manufacturer becomes aware have been disposed of in violation of applicable state and local laws and regulations; and 0
 - (iii) A description of any failure of a tire outlet to act in accordance with the directions in the manufacturer's plan, including an identification of the outlet(s) in question. na